

# Supplemental repro Instructions

## Balloons & accessories

### **Balloons qualityprint:**

- Use our working drawing.
- Submit files in vector.
- Always convert text to letter outlines.
- Deliver printing in the desired pantone color.
- Elements smaller than 1mm can disappear / be difficult to see and fill up.
- Round / square shapes may deform on this product..
- Differences in fitting cannot be avoided with the Qualityprint printing technique. This is only possible in the print quality High Quality Precision Print.

### **Balloons High Qulaity Precision Print:**

- Use our working drawing.
- We request that you show us the logo in advance so that we can give you our printing advice to give. Not all full color logos are printed in full color. Often extra spot colors are needed to be printed to achieve the best result.
- Always convert text to letter outlines.
- Deliver printing in the desired pantone color.
- Elements smaller than 1mm can disappear / be difficult to see and can closing.
- Round / square shapes may deform on this product.

### **Giant Balloons qualityprint:**

- Use our working drawing.
- Submit files in vector.
- Always convert text to letter outlines.
- Deliver printing in the desired pantone color.
- Elements smaller than 1mm can disappear / be difficult to see and can closing.
- Round / square shapes may deform on this product.

- Differences in fitting cannot be avoided with the Qualityprint printing technique, we request that you do so show us a multi-color printing image in advance so that we can give you our printing advice.

### **Punchballs Qualityprint**

- Use our working drawing.
- Submit files in vector.
- Always convert text to letter outlines.
- Deliver printing in the desired pantone color.
- Elements smaller than 1mm can disappear / be difficult to see and can closing.
- Round / square shapes may deform on this product.

### **Flags / pennants & flags**

#### **Paper handflags:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- Deliver both the front and rear.
- Take into account the adhesive strip in the design.
- Place text and important elements within the safety margins.
- For full color printing, supply black as = 50, m = 0, y = 0 and k = 100

**Supporters flags:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- Deliver both the front and rear.
- Take into account the adhesive strip in the design.
- Place text and important elements within the safety margins.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Flags and pennants:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- Leave 1 cm free of text and logos at the top.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100

**Bicycle flags:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- Leave 1 cm free of text and logos at the top.
- Deliver both the front and rear.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100

**Bunting punched shapes:**

- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- Leave 1 cm free of text and logos at the top.
- Deliver the punching line as a line, this line must be in overprint and a supporting color.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100

**Vertical Deco Garlands:**

- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- Deliver the punching line as a line, this line must be in overprint and a supporting color.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100

**Letter-banner:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- Deliver the punching line as a line, this line must be in overprint and a supporting color.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

# **Gastronomy**

## **Party picks standard:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 2.5 mm from the edge.

## **Party picks punched shapes:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 3 mm from the edge.

## **Burgerpicker:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 3.5 mm from the edge.

## **Gunshapes:**

- Use our working drawing.
- Submit files in vector.
- Always convert text to letter outlines.
- Elements smaller than 0.2 mm can disappear / be difficult to see and can closing.

**Paper cups:**

- Use our working drawing (do not deliver files in a bulge).
- Place logos and text within the blue frame in our working drawing.
- Round / square shapes may deform on this product.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Supply black as c = 50, m = 50, y = 50 and k = 100.
- Deliver files in cmyk full color.

**Popcorn box:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- Do not place a design on the adhesive strip and bottom.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Cardboard plates:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Beer coasters:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- Supply black as c = 100, m = 100, y = 20 and k = 100.
- Deliver files in full color.

**Paper cup holders:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge and drill holes.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Cutlery:**

- Use our working drawing.
- Submit files in vector.
- Always convert text to letter outlines.
- Elements smaller than 0.2 mm can disappear / be difficult to see and can closing.

**Masks and hats****Sunvisors & crowns:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.

- Always include links.
- Place logos and text at least 5 mm from the edge and drill holes.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Masks with elastic:**

- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Deliver the punching line as a line, this line must be in overprint and a supporting color.
- Place logos and text at least 5 mm from the edge and drill holes.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.



**Masks with sticks:**

- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Deliver the punching line as a line, this line must be in overprint and a supporting color.
- Place logos and text at least 5 mm from the edge and drill holes..
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Eye masks and pirate eye patch:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge and drill holes.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Chef's hats:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Crown hats:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Party hats:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge and drill holes.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Indian headbands:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Pirate caps:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge and drill holes.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Carnival Signs:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Photo Props:**

- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links..
- Place logos and text at least 5 mm from the edge
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.
- Deliver the punching line as a line, this line must be in overprint and a supporting color.

**Promotion****Fan clappers:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Waving hands:**

- Use our working drawing.
- Deliver both the front and rear.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Party horns:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.
- Do not place a design on the part where the whistle is glued.

**Megaphones:**

- Use our working drawing.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Windmills:**

- Use our working drawing.
- Deliver both the front and rear.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Notepads:**

- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.

**Stickers screen printing:**

- Submit files in vector.
- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Place logos and text at least 5 mm from the edge.
- Supply files with the desired standard or pantone colors.

**Stickers Full Color Offset:**

- Always convert text to letter outlines.
- Submit files with 3 mm bleed all around.
- Always include links.
- Place logos and text at least 5 mm from the edge.
- With full color printing, supply black as = 50, m = 0, y = 0 and k = 100.